



925 Champlain St., Dieppe, N.B. E1A 5T6  
 PH. (506) 859-5817 FAX (506) 859-5809

**ESTIMATE OF REPAIR**

NAME		ADDRESS			PHONE	DATE
Ryder						April 11/23
YEAR	MAKE	MODEL	LICENSE	UNIT NO.	SERIAL NO.	
2013	Wabash	Pup Reefer	K80 80J	844122	1JJV322B7DL762583	
BODY MAKE		BODY MODEL		BODY SERIAL NUMBER		MILEAGE
						N/A
Labour hrs	OPERATION / JOB DESCRIPTION					PARTS TOTAL
1.5	Replace leaking hub cap gasket R2, Replace 3 missing hub cap bolts R1, Replace L2 hub cap.					\$52.00
3	Install aluminum plate over bottom rail corrosion left rear and just behind pick up plate left side.					\$75.00
40	Repair main lift gate platform.					\$475.00
3	Replace right hydraulic cylinder on lift gate.					\$1,820.00
2	Weld crack at right side top of extension plate and under extension plate as well.					\$10.00
1.5	Replace missing grease fittings (2) on lift gate and 1 on left side won't take grease.					\$15.00
0.5	Straighthen front diagonal dolly leg brace on left leg.					\$0.00
0.6	Clean up corroded battery terminal connections on lift gate batteries.					\$10.00
1	Repair tail light grommets and loose wiring on tail lights at rear lift gate steps.					\$30.00
3	Replace 3 center hinges on lower roll up door panel. Repair panel in order to fasten hinges.					\$40.00
1.5	Replace 5th and 7th rollers from bottom left on rear door.					\$30.00
0.7	Refasten right side e-track toward front on right side wall.					\$10.00
0.7	Replace leaking shock absorber L2.					\$70.00
0.8	Replace R2 slack adjuster.					\$120.00
3	Perform 1 wheel brake job R2 including brake drum and brake cam and bushings.					\$318.00
1	Repair cause of ABS light not working. (Valve is cycling.)					\$20.00
	Note: Needs tire repair L2 inner, currently has 65 psi.					
63.8						
<p>The above is an estimate, based on our inspection, and does not cover additional parts and labour which may be required after the repair order has been open. Occasionally, after work has started, worn, broken or damaged parts are discovered which are not evident on first inspection. Quotation on a part and labour are current and subject to change.</p> <p>EST. MADE BY: _____ J-R Gaudet</p>					<b>SUBLETS</b>	
					<b>TOTAL LABOUR</b>	\$5,742.00
					<b>TOTAL PARTS</b>	\$3,095.00
					<b>SHOP SUPPLIES</b>	\$200.00
					<b>SUB-TOTAL</b>	\$9,037.00
					<b>HST</b>	\$1,355.55
					<b>TOTAL ESTIMATE</b>	\$10,392.55

**AUTHORIZATION FOR REPAIR.** You are hereby authorized to make the above specified repairs to the unit description herein.

**SIGNED:** \_\_\_\_\_

**DATE:** \_\_\_\_\_